

	Type	L #	Hits	Search Text	DBs	Time Stamp	Err Co m or m Defini nts tio n	Err or s
1	BRS	L6	2006	((piezoelectric or quartz or crystal or saw) and amplifiers and phase and shift and feedback and oscillat\$4)	US-PGPUB	2006/01/09 15:22		
2	BRS	L7	23	((piezoelectric or quartz or crystal or saw) and amplifiers and phase and shift and feedback and oscillat\$4).clm.	US-PGPUB	2006/01/09 15:22		
3	BRS	L8	379	331/135.ccis.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/01/09 15:32		
4	BRS	L9	1445	331/158.ccis.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/01/09 15:32		